A 700/900mW/Channel CMOS Dual Analog Front-End IC for VDSL with Integrated 11.5/14.5dBm Line Drivers

M. Moyal, M. Groepl, H. Werker, G. Mitteregger, J. Schambacher

Xignal Technologies AG, Munich, Germany


BEST AVAILABLE COPY

Outline

Dual Channel VDSL AFE


- Overview
- Architecture
- Circuit Implementations
- Measured Performances
- Summary

Overview




- VDSL-AFE for CO and CPE
- 0.25/0.5µm 5M 1P CMOS, MIM-Capacitors, Poly-Resistors
- Emphasis on power saving
- Almost no external components

Overview continued




,


Architecture Per Channel



Transmitter Implementation: DAC




Fransmitter: Post Filter



- 4th order Butterworth, f-3dB 18MHz, calibrated at power up
- 14dB Power back-off in 1dB steps


OPAMP CONCEPT




₽ Tip VSS վ**Էgm1**՟ 0 0 ال gm2 َ اً gm3 \mathfrak{O} \mathbb{Q} gm5 C2 C3 լ_,gm4_⋆ 0 0 **P C6** C7 **N C5** →outp **⇔outm**

OPAMP CORE


Line Driver




Hybrid / VGA




Hybrid / VGA (next revision)




ADC




ADC GM-STAGE



ADC COMPARATOR




LC-PLL CIRCUIT



Measurements


- Transmit Path and Line Driver
- Receive Path
- PLL

Transmit Path- Measurement 1



14.5 dBm signals for power measurements and functional tests


Fransmit Path- Measurement 2




THD in 12MHz:

- 72 dBc @1.9MHz(0dBfs)
- 74 dBc @1.9MHz(- 3dBfs)

Line Driver IM3-Measurement




Receive Path- Measurement




2.1MHz (-1dBfs) 14 dB VGA gain BW = 12MHz SNR = 72dB THD = 71dB

240MHz-PLL Measurement



30MHz input 240MHz output

Jitter: 12ps(rms)



Summary

- Dual Channel VDSL AFE
- Integrated Line Driver
- 900mW/channel power consumption at 14.5dBm line power
- 23mm²/channel (31mm² with test structures)
- 12b TX-performance at 12MHz signal bandwidth
- 12b RX-performance at 12MHz signal bandwidth

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ skewed/slanted images
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
\square REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
□ other:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.